

**ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF NONCOMPLIANCE  
INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. **03V-060** by the  
National Highway Traffic Safety Administration

**Part 573 Report Date:** January 30, 2003

**Date Faxed:** February 24, 2002

**Manufacturer:** Winnebago Industries

**Manufacturer Contact:** Mr. Dale Jordal  
Product Safety Administrator

**FAX:** (641) 585-6966


**SUBJECT:** 8,532 Winnebago 2000-2003 Sightseer, Brave, Adventure, and Itasca 2000-2003 Sunova, Sunrise, and Suncruiser motorhomes built on the Ford F53 motorhome chassis manufactured from August 1999 through January 2003. The brake system warning indicator may not function as required by Federal Motor Vehicle Safety Standard No. 105, "Hydraulic and Electric Brake Systems." The brake system warning indicator may not illuminate when the ignition is in the start position or for a low brake fluid condition.

This is an acknowledgment for this recall. A formal acknowledgment letter will be written only if we have additional comments or concerns.

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in your report, Ford (02V-327) will conduct the recall.

If you have any questions, please call:

  
Judith Taylor, Safety Recall Analyst on (202) 366-9525 or  
George Person, Chief on (202) 366-5210  
or Fax at (202) 366-7882  
or e-mail at [Judy.Taylor@nhtsa.dot.gov](mailto:Judy.Taylor@nhtsa.dot.gov)  
Recall Management Division